# RISK PRIORITIZATION OF ENVIRONMENTAL ASPECTS AND OCCUPATIONAL HEALTH SAFETY IN TEXTILE INDUSTRIES OF GAZIPUR INDUSTRIAL AREA, BANGLADESH

# Md. Iftakharul Muhib Assistant Professor

General Education Department City University, Dhaka, Bangladesh E-mail: muhibiftakhar@gmail.com

#### Md. Shawkut Ali Khan Professor & Head

Department of Mechanical Engineering City University, Dhaka, Bangladesh E-mail: shawkutali8@gmail.com

#### Rifat Akter Post Graduate Student

Department of Microbiology Jagannath University, Dhaka, Bangladesh E-mail: rifatakter5@gmail.com

## ABSTRACT

Though textile industries are the backbone of country's economy; it possesses the environmental and occupational health safety risks also. After the Rana Plaza tragedy, the environmental and occupational health safety regulations become started to come spotlight. However, still there found anomalies that threaten environmental and occupational health safety. So to get an overview of present risk levels in different industries, the aim of this study was set to evaluate the risk prioritization for both environmental aspects and occupational health safety. A total of 10 textile industries were selected and a direct field survey along with an interview from workers to top management was done to conduct the study. Risk assessment results for environmental aspects showed that water pollution shows a moderate risk rating value while air quality, soil quality, noise, waste generation, hazardous material handling, and miscellaneous use showed low risks. Again calculated results for occupational health safety showed that necessary action is recommended to avoid future risk in all-hazard categories of different types except for electrical hazards. Controlling measures were suggested in accordance with the risk priority. Thus it is high time to explore and evaluate the risk level and take necessary action on the resultant priority basis.

Keywords: Environmental Aspects, Occupational Health Safety, Risk, RPN, Textile Industry.

## INTRODUCTION

Textile industries play a pivotal role in the rapid economic growth of Bangladesh (World Bank, 2012). The contribution of the textile sector to the country's total export revenue is more than 80% that is 28 billion USD/year and the projected revenue is 50 billion USD by the tear of 2021 (Hossain et al., 2018). However, this great success comes with environmental deterioration along with occupational health safety risks. Different types of environmental aspects like water discharge, air quality, soil

quality, noise, waste generation, energy consumed, a resource used, hazardous materials storage, and miscellaneous issues were considered to be major sources of environmental impacts in the Gazipur industrial area. Heavy metals like Cr, Ni, Zn, Hg, Ob, Cu, Cd, As, etc. are released from the textile industries that pollute the river, soil, and consequently the food chain when this polluted water is used for irrigation purpose to cultivate the seasonal crops (Islam et al., 2013). Several occupational health hazards are found in the textile industries of Bangladesh. Some of them were so drastic that international textile market trade was likely to fall on its edge. One of the worst examples is the Rana plaza accidental disaster in 2013 that killed over 1100 workers and the devastating fire of Tajreen garments in 2012 killed over 100 workers (Khan, 2017). So risk leveling of environmental aspects and occupational health safety along with their remedial measures is very important to avoid the disaster. However, enforcement of these remedial in perspective of risk rating is very much challenging. The reasons for enforcement hindrance are insufficient resources (knowledge, human resource, and funds), the unwillingness of industry owners, economic corruption, political imbalance, and inadequate coordination among the concerned agencies. Since there is no sufficient data for risk evaluation of environmental aspects and occupational health safety hazards, this study could act as a baseline survey for further rigorous study regarding the environmental and occupational compliance sector of Bangladesh.

#### METHODOLOGY

This study was conducted to confine the current status of environmental aspects and occupational health safety scenarios in the scale of risk evaluation to develop a research hypothesis. A total of 10 different textile industries in the Gazipur area were selected to conduct the survey. This survey was designed to collect information about the environmental aspects and occupational health safety practices in the selected industries directly from the field survey as well as interviewed from the worker to top management. All the collected data were processed and analyzed chronologically. One of the real constraints of the investigation was their privacy maintenance. Taking pictures and gathering information inside the factory premises were very much challenging since the authorities didn't want to disclose their in site scenario publicly. Therefore none of the names of studied industries are disclosed in this manuscript.

### **Data Responders**

A total of 490 respondents were selected from 10 industries where 100 data responders (10 from each industry) from management and 390 respondents (39 from each industry) from the worker level. In this analysis, about 98% (38 out of 39 respondents) of management body know very well about environmental and occupational compliance while only 15% (59 out of 390 respondents) workers know about these compliances in very primary level and rest of 85% (331 out of 390 respondents) workers know nothing about this matter.

### **Risk Evaluation for Environmental Aspects**

The identification of environmental aspects and impacts is important to the selection of environmental safeguards and work methods for operational activities. Risk evaluation of environmental aspects depicts the magnitude of potential consequence (level of environmental impacts) and the likelihood (level of probability of occurrence) (PERSEUS, 2012).

### **Risk** (**R**) = Likelihood (L) × Consequence (C)

This C×L matrix displays the qualitative or semi-quantitative rating of consequence and likelihood that specific data will occur to generate a risk score and risk rating. Risk rating data shows the level of risk in absence of a controlled environment and is arrived at after measuring the livelihood and the consequence of an event occurring (Endeavour Technical Limited, 2015).

### **Risk Evaluation for Occupational Health Safety**

The Failure Mode and Impact Analysis (FMEA) method are followed for occupational risk safety analysis (Yari, 2017; Wang et al., 2018). This method enhances the safety and reliability level by providing early detection and elimination of failures (SAE International, 2020). In this way, risk prioritization is done by taking into the multiplication of severity, probability, and detectability that is known as Risk Priority Number or RPN (Yang & Wang, 2015; Zhang & Chu, 2011).

## **RPN** = Severity × Probability × Detectability

Here, severity is the consequence of the failure; occurrence is the probability or the frequency of failure occurring, and detection is the probability of the failure being detected before the impact of the effect is realized. If the RPN result crosses 100, necessary action is recommended. The maximum value of RPN is 1000 (Kumar et al., 2014).

## **RESULTS AND DISCUSSION**

### **Risk Rating for Environmental Aspects**

Environmental aspects can be attributed to the activity that interferes with the natural environmental condition called the impact that is the resultant of an aspect (Susanto & Mulyono, 2018).

Environmental	Potential	Identified		<b>Risk Evaluation</b>		Risk Rating		<b>Control Measures/Mitigation</b>	
Aspects	Impacts	Risk	Likeliho	ood	Consequence	e e e e e e e e e e e e e e e e e e e			
			Condition	Score	Condition	Score	Score	Level of Risk	
Water Discharge	Water Pollution	>Disposal of chemical. >Effluent from ETP. >Disposal of used oil for machine maintenan ces. >Sewage discharge	Possible	3	Moderate	2	6	Modera te Risk	>Chemical store should be maintained properly. >Optimization of Effluent Treatment Plant (ETP) operation is highly recommended.
Air Quality	Air Pollution and Dust Emission	Dust and other exhaust atmospher ic emission of SO <sub>2</sub> , NO <sub>x</sub> , CO, SPM, etc. occur due to the stack gas of generator and vehicular movement in and outside of the factory area.	Possible	3	Minor	1	3	Low Risk	<ul> <li>&gt;Factory chimney should be functional 24/7.</li> <li>&gt;Water spraying can be done to reduce dust pollution on the nearby road.</li> <li>&gt;Ensuring vehicles, generators, compressors are well maintained.</li> <li>&gt;Proper ventilation system should be designed.</li> <li>&gt;Use of PPE like a mask, apron should be used mandatorily</li> </ul>
Soil Quality	Soil Pollution	>Leakage of oil from vehicles	Unlikely	2	Moderate	2	4	Low Risk	>Proper solid waste management should be followed

Table 1. Risk Assessment Level of Environmental Aspects

				-					
	and Erosion	and other maintenan ce works >Mainten ance work that excavates soil. >Chemica 1 spillage	D. U.			-			
Noise	Noise Pollution	>Noise is generated from vehicle movement , operation of the generator, compress or, and other heavy vibrating types of machinery	Possible	3	Minor	1	3	Low Risk	More use of PPE like earplug/ear muffs in noisy workplace
Waste Generation	Surroundi ng Environm ental Pollution	<ul> <li>&gt;Impact         <ul> <li>of</li> <li>disposal</li> <li>waste</li> <li>&gt;Hazardo</li> <li>us</li> <li>chemical/</li> <li>biomedica</li> <li>l waste.</li> <li>&gt;Non-</li> <li>persistent</li> <li>material</li> <li>e.g. paper,</li> <li>cardboard,</li> <li>etc.</li> <li>&gt;Persistent</li> <li>t material</li> <li>e.g.</li> <li>plastic,</li> <li>scrap, etc.</li> <li>&gt;E-waste.</li> <li>&gt;Kitchen</li> </ul> </li> </ul>	Possible	3	Minor	1	3	Low Risk	>Introducing 3R (Reduce, Reuse, Recycle) waste management. >Medical waste generated by the factory should be handed over to the local hospital.
Energy Used	Power Consumpt ion	>Chemica l/oil spillage in the generator room. >Pb, Cd, Hg pollution from scrap battery and solar panel	Unlikely	2	Minor	1	2	No- Risk	>Handling of chemicals and oil should be done properly. >Older battery and solar panel should be disposed of properly
Resources Used	Infrastruct ure Developm ent	>Land. >Building > types of machinery >Tools. >Trees etc.	Unlikely	2	Minor	1	2	No- Risk	>Land management and building design should be done properly.
Ecological View (Flora & Fauna)	Loss of Habitat of some Flora and	>Unplann ed constructi	Unlikely	2	Minor	1	2	No- Risk	>Maintain maximum vegetation. >Implementation of agroforestry techniques well adapted to the site.

	Fauna and Biodiversi ty Reduction	on and design >Inapprop riate control of weeds							
Hazardous Materials Storage and Handling	Occurrenc e of accidents	Accidenta l spillage and fire occur due to personal error or natural events.	Unlikely	2	Moderate	2	4	Low Risk	>Proper inspection of maintenance and storage of hazardous goods should be monitored regularly.
Miscellaneous Issues	Others Incidents	>Imbalan ce of political condition. >Worker imbalance >Producti on loss. >Visual appearanc e.	Unlikely	2	Moderate	2	4	Low Risk	>Management should be aware of workers legal demand

There is a significant amount of water, energy and other resources are consumed by the studied industries. Based on an environmental point of view, a list of environmental; aspects, their risk rating along controlling measures are organized in Table 1. A moderate risk rating was found for water pollution impacts. Though there was ETP in most of the studied industries, there showed some anomalies like ETP did not run 24 hours, lack of ETP servicing hindered the ETP efficiency, personal error, maintenance, and chemical cost and last but not least is the lack of ETP performance optimization. Other environmental aspects like soil quality, air quality, noise, waste generation, hazardous material handling, and miscellaneous issues though were found to be possessed low risk, they could be upgraded to more negative risk levels in the near future if a proper controlling measure is not taken immediately. However environmental aspects like energy used, a resource used, and ecological view in the industrial area were found to be relatively at the safe level from risk. All the control measures are given accordingly.

### **Risk Rating for Occupational Health and Safety**

Spinning, weaving, dyeing, printing, and garments sections were studied in the 10 industries. Hazards occurred in these industries are classified into 7 different categories- physical hazard, fire hazard, electrical hazard, chemical hazard, ergonomic hazard, psychosocial hazard, and biological hazard. These categories were subdivided into different hazard types. The consequences of these hazards were rated with an RPN number to recommend whether necessary action would be required or not (Table 2). Remedial measures are also listed in the same table. Risk prioritization is found for most of the hazard types. The highest number of RPN (RPN=384) was found for hazard type of dyes from the chemical hazard category that causes water pollution in the nearby water bodies though ETP was found in almost all the surveyed industries. The cause of this RPN number either the lack of proper operational optimization or lack of proper handling of dyes materials. These dyes material are hazardous to workers' health. For example, dyes can cause skin and eye irritation, lung inflammation, and other respiratory problems (Bansal & Yadhav, 2016).

# Table 2. Risk Leveling of Occupational Health Hazards

Hazard	Hazard Type	Consequences	RPN	Necessity	Remedial
Category			(Probability×Detection×Severity)	of Action	Measures
Physical	Noise	Hearing loss	10×6×6=360	Action	>Proper
Hazard				Required	servicing of
					the heavy
					types of
					machinery.
					>Use of
					soundproof
					and corplug
	Duet	Respiratory	8~7~6-336	Action	
	Dust	Disease	0~7~0=550	Required	housekeeni
		Disease		Required	ng
					>Use of
					PPE widely
	Light	Eye stress	3×3×3=27	Not	>Optimized
	0			Required	light set up
	Temperature	High	8×6×6=288	Action	>High
		temperature		Required	temperature
		create			in the
		dehydration			working
		and blood			place should
		pressure			be
	Turning	anomalies	4.2.2.26	NL	controlled
	Ventilation	Lung function	4×3×3=36	Not	>Proper
	ventilation	Change		Kequiieu	system
					should be
					installed
Fire Hazard	Welding	Spark ignition	3×2×3=18	Not	>Restrict
	6			Required	the welding
				_	area for
					movement
	Smoking	Common	5×4×5=100	Action	>Smoking
		accidental		Required	should be
		source			banned in
					the working
					place.
					sign should
					be
					maintained
Electrical	Improper	Trip occurs	3×2×3=18	Not	>Should
Hazard	Earthing	T		Required	check
	0			1	earthing
					connection
					properly
	Short Circuit	A common	5×3×6=90	Not	>Air Circuit
		source of the		Required	breaker and
		fire accident			motor
					circuit
					breaker
					snould be
	Improper	Electric shock	3~3~1-36	Not	All circuite
	Isolation	Lieure shoek	57577-50	Required	should be
	-				

					. 11 1
					installed
					properly.
	Motor Rotation	Problems	3×3×3=27	Not	>Individual
	in High	occur in		Required	circuit
	Voltage	machine			breaker
		performance			should be
					installed.
	Old Wiring	Anomalies in	6×4×4=96	Not	Check for
		current flow		Required	old wiring
					to avoid
					accidents.
	Power Input-	Power shut	3×4×2=24	Not	>Wiring
	Output	down		Required	should be
	Imbalance			_	done
					according to
					the
					standards.
Chemical	Dyes	Skin and lung	8×6×8=384	Action	>ETP must
Hazard	-	disease		Required	be installed
				1	with
					optimizatio
					n
	Different	Skin and lung	7×6×6=252	Action	>Proper
	Types of	disease		Required	handling
	Chemical			1	and storage
					should be
					followed
	Used oil and	Skin and lung	6×5×5=150	Action	>Proper
	grease	disease		Required	handling
					and storage
					should be
					followed
Ergonomic	Uncomfortable	Leg and hand	4×4×3=48	Not	>Should
Hazard	Work station	pain		Required	give
					importance
					to
					ergonomics
	Repetitive	Wrist, neck,	6×5×6=180	Action	>Proper
	Strain Injuries	shoulder, knee		Required	working
		pain			procedure
					should be
					followed.
	Improper	Wrist, neck	4×4×4=64	Not	>Proper
	Handling of	pain		Required	handling
	Material				and storage
					should be
					followed
	Poorly	Hand pain,	2×3×4=24	Not	>Proper
	Designed Work	back pain		Required	working
	Practice				procedure
					should be
					followed
	Long Time	Headache,	5×5×6=150	Action	>Should
	sitting	dizziness,		Required	take a break
		nausea			at least 5
					minutes
					atter 1-hour
					documental
					work

	Heavy Weight Lifting	Back pain	3×3×3=27	Not Required	>Should not uplift the heavyweigh t alone
	Unsafe Work Place	Accidents may occur	3×3×4=36	Not Required	Working place should be designed with safety measures.
Psychosocial Hazard	Not Interested to Work willingly due to lack of Motivation	Physiological problem	7×5×6=210	Action Required	>Working department should be favorable. >Holiday, bonus, salary should be given properly
	Production Target	Stress	6×5×5=150	Action Required	The working department should be favorable.
	Increased Workload	Stress, heart rate changes	7×6×6=252	Action Required	The workload should be distributed evenly.
	Night Shift	Headache, dizziness, nausea	5×4×5=100	Action Required	The working department should be favorable.
	Over Time	Stress, tiered	5×5×5=125	Action Required	The working department should be favorable.
Biological Hazard	Contagious Diseases	Fever, pox, TB, Covid-19	5×5×5=125	Action Required	Always should be cautious about if a person feels ill or affected by any other disease especially contagious disease.

The least RPN number (RPN=18) was found for improper earthing of electrical hazard. This means that earthing was found to be done properly in all the studied industries. According to the RPN data, the descending order of listed hazards are leveled in the following order- physical hazard: noise>dust>temperature>improper ventilation>light; fire hazard: smoking>welding; an electrical hazard: old wiring>short circuit>improper isolation>high voltage motor rotation>power input-output imbalance; a chemical hazard: dyes>chemicals>used oil and grease; an ergonomic hazard: repetitive

strain injury>long time sitting>Improper material handling>Uncomfortable work station>unsafe work place>heavy weight lifting>poorly designed work practice; a psychosocial hazard: increased work load>willingness to work>production target>over time>night shift. This type of risk prioritization is also done by Kumar et al. (2014); Liu et al. (2012) and Chang (2016). The resultants o these RPN values make the risk understandable and recommend taking necessary action whether it is necessary or not to minimize it to a tolerable level. Infection of COVID-19 also seems to be hazardous (Shuvro & Talukdar, 2020).

#### CONCLUSION

Textile industries in the Gazipur area are confronted with a number of significant environmental and occupational health safety challenges. However, none of these challenges are unfeasible to overcome. The resultant risk leveling data for both environmental and occupational health safety scenarios would be of great use to policymakers, urban authorities, planners, researchers, and stalk holders of the industries for exploring towards sustainable development of the country.

#### ACKNOWLEDGEMENT

The authors are grateful to the studied industry's top management for giving permission to conduct the survey. The authors have no conflict of interest regarding this study. No funds, grants, or other supports were received. Authors Contribution: Md. Itakharul Muhib: Conceptualization, methodology, investigation, writing original draft; Md. Shawkut Ali Khan: Validation, supervision; Rifat Akter: Writing, review, and editing.

#### REFERENCES

- Bansal, M., & Yadav, R. K. (2016). Occupational Health Hazards and Awareness of Occupational Safety Among Workers Of Textile Dyeing Industries In Jaipur, India. OCCUPATIONAL HEALTH, 2(2), 30-38.
- Chang, K. H. (2016). Generalized multi-attribute failure mode analysis. *Neurocomputing*, 175, 90-100.
- Endeavour Technical Limited. (2015). ISO 14001: 2015. Control of Environmental Aspects & Impacts. Retrieved from https://www.iso-9001-checklist.co.uk/download/ISO-14001-2015-environmental-aspects-and-impacts-procedure-sample.pdf
- Hossain, L., Sarker, S. K., & Khan, M. S. (2018). Evaluation of Present and Future Wastewater Impacts of Textile Dyeing Industries in Bangladesh. *Environmental Development*, 26, 23–33.
- Islam, M. R., Jahiruddin, M., Islam, M. R., & Alim, M. A. (2013). Consumption of unsafe foods: Evidence from heavy metal, mineral and trace element contamination. *The National Food Policy Capacity Strengthening Programme (NFPCSP) sponsored project, Dept. of Soil Science, BAU, Mymensingh.* Retrieved from http://fpmu.gov.bd/agridrupal/content/consumption-unsafe-foods-heavy-metal-mineral-andtrace-element-contamination
- Khan, M. Z. H. (2017). Environmental Management System of Textile Industry in Bangladesh: Constraints and Remediation. International *Jour of Environment, Ecology, Family and Urban Studies*, 7(2), 1-12.
- Kumar, P. M., Mugundhan, K., & Visagavel, K. (2014). Occupational Health and Safety in Textile Industry. *International Journal of Research in Engineering and Technology*, *3*(11), 168-172.

- Liu, H. C., Liu, L., Liu, N., & Mao, L. X. (2012). Risk evaluation in failure mode and effects analysis with extended VIKOR method under fuzzy environment. *Expert Systems with Application*, 39(17), 12926-12934
- PERSEUS. (2012). AMP Tool Box, Key Activity 4. Qualitative Risk Analysis. Retrieved from http://www.perseus-net.eu/site/content.php?artid=2204.
- Shuvro, R. A., & Talukder, M. M. (2020). Impact of "COVID-19" on the Life of Destitute People: A Soft-Measurement in Bangladesh. Bangladesh Journal of Multidisciplinary Scientific Research, 2(2). https://doi.org/10.46281/bjmsr.v2i2.723
- Susanto, A. & Mulyono, N. B. (2018). Risk Assessment Method for Identification of Environmental Aspects and Impacts at Ore Processing Industry in Indonesia. *Journal of Ecological Engineering*, 19(2), 72-80.
- SAE International. (2020). Recommended Failure Modes and Effects Analysis (FMEA) Practices for Non-Automobile Applications. Retrieved from https://www.sae.org/standards/content/arp5580
- Wang, W., Liu, X., Qin, Y., & Fu, Y. (2018). A risk evaluation and prioritization method for FMEA with prospect theory and Choquet integral. *Safety Science*, *110*, 152-163.
- World Bank. (2012). Overview. Vol. 1 of Bangladesh—Towards Accelerated, Inclusive and Sustainable Growth: Opportunities and Challenges; *World Bank: Washington, DC, USA*.
- Yang, Z., & Wang, J. (2015). Use of fuzzy risk assessment in FMEA of offshore engineering systems. Ocean Engineering, 95, 195-204.
- Yari, S. (2017). Assessment of potential risk by the failure mode and effects analysis in an air conditioning equipment manufacturing company. *Jour of Safety Promotion and Injury Prevention, 5*(2).
- Zhang, Z., & Chu, X. (2011). Risk prioritization in failure mode and effects analysis under uncertainty. *Expert Systems with Applications*. 38(1), 206-214.

## Copyrights

Copyright for this article is retained by the author(s), with first publication rights granted to the journal. This is an open-access article distributed under the terms and conditions of the Creative Commons Attribution license (http://creativecommons.org/licenses/by/4.0/)